

In the Drawings

The attached replacement and annotated sheet(s) of drawings include changes to FIG. 1 and FIG. 2 as follows:

FIG. 1 has been amended such that box 121 has been relabeled 139 for consistency with the specification, and the descriptive legend has been changed from “chordic converter” to “cordic converter” to thereby correct the misspelling.

FIG. 2 has been amended to re-route the connection 237 to the delay element 238, and to insert cordic converter 139 of FIG. 1 in its proper place for consistency with FIG. 1 and the remainder of the description.

Attachment: Replacement Sheet

Annotated Sheet Showing Changes



Robert E. Krebs, Thelen Reid & Priest, LLP

Serial No.: 09/885,811

Filed: June 19, 2001

TRP Docket No.: 034942-245
Annotated Sheet Showing Changes




Fig. 1




Fig. 1



ROBERT E. KREBS, THELEN REID & PRIEST LLP
 Serial No.: 09/885,811
 Filed: June 19, 2001
 TRP DOCKET NO.: 034942-245
 Annotated Sheet Showing Changes




Fig. 2




Fig. 2